
Water Pump: Service and Repair

Coolant Pump - 2.3L

Material	
Item	Specification
Motorcraft Premium Gold Engine Coolant with Bittering Agent (bittered in US only VC-7-B (US); CVC-7-A (Canada); or equivalent (yellow color)	^{/)} WSS-M97B51-A1



ltem	Part Number	Description
1	8507	Coolant pump O-ring seal
2	8501	Coolant pump
3	W500015	Coolant pump bolt (3 required)
4	8509	Coolant pump pulley
5	W500221	Coolant pump pulley bolt (3 required)

Removal and Installation

- 1. Remove the Air Cleaner (ACL) outlet pipe. For additional information, refer to Fuel Delivery and Air Induction.
- 2. Drain the cooling system. For additional information, refer to Cooling System Draining, Filling and Bleeding 2.3L See: Cooling System/Service and Repair/Cooling System Draining, Filling and Bleeding.
- 3. Remove the drive belt. For additional information, refer to Drive Belts, Mounts, Brackets and Accessories.
- 4. Remove the 3 bolts and the coolant pump pulley.To install, tighten to 20 Nm (177 lb-in).
- 5. Remove the 3 bolts and the coolant pump.
 To install, tighten to 10 Nm (89 lb-in).
- 6. NOTE: Lubricate the coolant pump O-ring seal with clean coolant.

To install, reverse the removal procedure.